

EQUIPMENT INTERCHANGE REPORT — CONTAINER INSPECTION

LIMITED COVERAGE

This inspection does not cover all required views. 1 of 8 required views were photographed. Not photographed: Rear / Doors, Left side, Right side, Roof, Floor, Understructure, Interior. No statement is made about the condition of the surfaces that were not photographed.

ContainerHub Demo

Valencia, Colombia
demo@containerhub.com

Document
EIR-82JZ9U4X6X

Inspection date
2026-08-19

Issued
2026-08-19 16:39 UTC

CONTAINER IDENTITY (frozen at inspection)

Container no. HANU8374480	Size Not stated	Type Not stated	ISO code Not stated
Customer Not stated	Inspection type ENTRY	Inventory record Standalone inspection	Identity source AT_INSPECTION

CONFIGURATION APPLIED

Profile ContainerHub Baseline v1	Profile version ch_profile_baseline_v1	Selected AUTO	Automated rules None executed
--	--	-------------------------	---

COVERAGE — 1/8 required views

Surface	Photographed	Photos
Front	Yes	p1
Rear / Doors	No	—
Left side	No	—
Right side	No	—
Roof	No	—
Floor	No	—
Understructure	No	—
Interior	No	—

PHOTOGRAPHIC EVIDENCE

Ref	View	Analysed	Note
p1	FRONT	Yes	INCLUDED

FINDINGS — 3 observations

1. DENT — LEFT_WALL

MODERATE · AI proposed

EVIDENCE
p1 (primary)



p1 - area outlined by Demo Inspector

ORIGINAL AI OBSERVATION (UNEDITED)
DENT — LEFT_WALL · MODERATE · model confidence 0.90
Abolladuras visibles en la estructura del panel lateral.
INSPECTOR DECISION

#1 REPAIR_REQUIRED (Demo Inspector, COMPANY_ADMIN, 2026-08-19 14:51 UTC)
REPAIR CODING
Not coded — no repair coding catalogue is configured. No code or cost is stated.

2. DENT — DOORS

MINOR · AI proposed

EVIDENCE
p1 (primary)



p1 - area outlined by Demo Inspector

ORIGINAL AI OBSERVATION (UNEDITED)
DENT — DOORS · MINOR · model confidence 0.85
Deformaciones leves en la superficie de las puertas.
INSPECTOR DECISION

#1 OBSERVE (Demo Inspector, COMPANY_ADMIN, 2026-08-19 14:52 UTC)
REPAIR CODING
Not coded — no repair coding catalogue is configured. No code or cost is stated.

EVIDENCE
p1 (primary)



p1 - area outlined by Demo Inspector

ORIGINAL AI OBSERVATION (UNEDITED)
CORROSION — CORNER_CASTINGS · MINOR · model confidence 0.80
Corrosión superficial en los elementos de la base.

INSPECTOR DECISION

#1 ACCEPTABLE (Demo Inspector, COMPANY_ADMIN, 2026-08-19 14:52 UTC)

REPAIR CODING
Not coded — no repair coding catalogue is configured. No code or cost is stated.

SCOPE OF THIS REPORT

This report states what was photographed, what an AI model proposed, what a person corrected and what a person decided. It does not assess compliance with IICL, CSC or any other external standard: no such criteria were applied. No automated decision rules were executed — every decision above was taken by the named person. Where a marked location is given, it is the area a named person outlined on the photograph: not a measurement of the container, and not produced by the model. Repair codes and costs are not stated because no repair coding catalogue is configured.